
















1. EQUIPMENT

- 1.1. Cube press calibrated as per **QTP03** (*Laboratory equipment calibration checking and maintenance*) & checked as per **QTF11** (*Checking platens & loading rate*) AND
- 1.2. Scale with an accuracy of 1 g, calibrated as per **QTP03** & checked as per **QTF08** (*Checking scale [across range]*)

2. METHOD

2.1. Preparation -

- 2.1.1. Ensure that the person that does the compression strength testing wear all the relevant personal protective equipment;

MARK "X" FOR APPLICABLE PERSONAL PROTECTIVE EQUIPMENT REQUIRED		
	Hard Hat	
	Eye Protection	X
	Face Protection: Welding Helmet	
	Hand Protection	X
	Protective Clothing: Overall	X
	Foot Wear: Safety Boots	X
	Gum boots	
	Dust mask	X
	Respirator	
	Reflective Clothing	X
	Safety Harness	
	Apron	
	Hearing Protection	X
	Use waste bins for waste separation	X
	Lock-out	X

- 2.1.2. Conduct continuous risk assessment, the daily safe task instruction (*DSTI*);

- 2.1.3. Wear gloves & eye protection now;

- 2.1.4. Check the calibration label on the compression machine if it is still valid (*expiry date not lapsed*), if the date has expired report this to your manager (*do not test any cubes!*);

- 2.1.5. Check the compression machine that it is operational, safe & not contaminated;

- 2.1.6. Check the calibration label on the scale if it is still valid (*expiry date not lapsed*), if the date has expired report this to your manager;

- 2.1.7. Check the scale is operational, safe & be aware of electrical hazards that can cause serious injury & damage incidents and



2.1.8. Make & cure test specimens as per **QTW02** (*Making & curing test cubes*);

Note: Any specimens received dry are saturated for at least 24 hours prior to testing.

3. PROCEDURE

3.1. Testing Cubes:

- Immediately before testing, remove cubes (*as per crushing date on the label*) from the water bath & wipe excess moisture from all surfaces;
- Weigh each cube, & record mass in kg on the relevant **QPF22** (*Call report*) Cube Worksheet (see **QTW01**);
- If cubes will not be crushed immediately after weighing, cover them with damp cloth or plastic to retain moisture;
- Ensure that the loading plate is not contaminated. Carefully center the specimen in the jaws of the machine with the cast surface (*top of cube*) facing forward & the smooth surfaces in contact with the top & bottom platen;
- Follow instructions for operating the crushing machine;
- Record the result of each test on the relevant form and
- Remove the crushed cube & discard in accordance with relevant environmental procedures.
- Carefully wipe all debris (*into a bucket*) from both top & bottom platens before crushing the next cube (*be aware of any hand injury hazards*).

3.2. Test Results:

- 3.2.1. Calculate individual compressive strength test results to the nearest 0.1 MPa, in accordance with cube size, eg. 150mm x 150mm x 150mm cubes & using the relevant calibration factor (*if any*) for the cube press;
- 3.2.2. Calculate the average strength of three cubes rounded to the nearest 0.5 Mpa (*where only two cubes are required, the average of two [2] results*).
- 3.2.3. Note any abnormal failures (*cubes not achieving expected strength, or failing in a pattern other than an hour-glass shape*) & retain the cube in a designated holding area for inspection by immediate supervisor;
- 3.2.4. Record the above on the relevant **QPF22** cube worksheet, & sign the cube worksheet **QPF22** to confirm that no abnormal failures were noted;
- 3.2.5. If cubes have been made for crushing at later date(s), file the cube worksheet **QPF22** for recording further results, e.g. for 28-day cubes.
- 3.2.6. Reporting results **QTF20** Compressive strength report & see **QTP06** reporting test results.

4. RECORDS

Note: Records generated as a result of this procedure are as follows:

ENTRY NUMBER	RECORD	LOCATION/ CUSTODIAN	MINIMUM RETENTION	DISPOSAL METHOD
--------------	--------	---------------------	-------------------	-----------------

Document Name: Compression Strength
Document Number: QTW3
Originator: © SARMA

Rev. No.: DC

Original Date: January 2012
Page: Page 2 of 3



			TIME	
4.1.	QTF08 Scale check (<i>across range</i>)	See QTP03 - Laboratory equipment calibration checking and maintenance		
4.2.	QTF11 Checking platens & loading rate	See QTP03 - Laboratory equipment calibration checking and maintenance		
4.3.	QTF20 Compressive strength report	Laboratory Assistant	1 year	Shred
4.4.	QTF22 Cube worksheet	Laboratory Assistant	1 year	Shred
4.5.	Cube press Calibration Certificate	Various		
4.6.	Scale Calibration Certificate	Various		

5. REFERENCES AND APPENDIXES

ENTRY NUMBER	ENTRY DESCRIPTION	REFERENCE NUMBER
5.1.	Calibration, checking & maintenance of laboratory equipment	QTP03
5.2.	Reporting test results	QTP06
5.3.	Slump test	QTW01
5.4.	Compression testing	SANS 5863:2006
5.5.	Scale Calibration Certificates	Various
5.6.	Making & curing test specimens	QTW02
5.7.	Risk Assessment Documentation (<i>DSTI</i>)	Various
5.8.	Personal Protective Equipment Issue Record	Various
5.9.	Personal Protective Equipment Checklist	Various
5.10.	Training Certificates	Various

TECHNICAL MANAGER NAME		DESIGNATION/ AREA	
TECHNICAL MANAGER SURNAME		Date	
TECHNICAL MANAGER SIGNATURE		IDENTITY NUMBER	

ACKNOWLEDGEMENT OF UNDERSTANDING OF HOW TO DO COMPRESSION TESTING

TECNICIAN NAME		DESIGNATION/ AREA	
TECHNICIAN SURNAME		Date	
TECHNICIAN SIGNATURE		IDENTITY NUMBER	